

EAST Search History**EAST Search History (Prior Art)**

Ref #	Hits	Search Query	Dbs	Default Operator	Plurals	Time Stamp
L5	4	ophthalmic near2 drill\$4 and calibrat \$4	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/09/24 12:16
L4	2	ophthalmic near lens near drill\$4 and calibrat\$4	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/09/24 12:16
L3	16	ophthalmic near lens near drill\$4	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/09/24 12:16
L2	6060	ophthalmic near lens	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/09/24 12:16
L1	6060	ophthalmic near lens	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/09/24 12:16
L8	8	ophthalmic with calibrat\$4 and reference adj mark	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/09/24 12:17
L7	18	ophthalmic with drill \$4 and calibrat\$4	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/09/24 12:17
L6	4	ophthalmic with drill \$4 with calibrat\$4	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/09/24 12:17

L14	246	drilling with calibrat \$4 same holes	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/09/24 12:48
L13	5	ophthalmic with calibrat\$4 and offset and template	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/09/24 12:48
L12	10	ophthalmic with calibrat\$4 and drill \$4 and lens	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/09/24 12:48
L11	57	ophthalmic with calibrat\$4 and offset	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/09/24 12:48
L10	7	ophthalmic with calibrat\$4 and reference adj mark and (mean averag \$4)	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/09/24 12:48
L9	2	ophthalmic with calibrat\$4 and reference adj mark and template	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/09/24 12:48
L18	12	(drilling bor\$4 mill \$4) with calibrat\$4 and programmable and camera and offset with compensat\$4	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/09/24 12:49
L17	14	(drilling bor\$4 mill \$4) with calibrat\$4 same template	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/09/24 12:49
L16	7	(drilling bor\$4 mill \$4) with calibrat\$4 same two near holes	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/09/24 12:49

L15	5	drilling with calibrat\$4 with two near holes	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/09/24 12:49
L20	7	((drilling bor\$4 mill \$4) with calibrat\$4 and programmable and determin\$7 with compar\$4 with locat\$4 not "Printing cartridge" not ink	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/09/24 12:50
L19	12	(drilling bor\$4 mill \$4) with calibrat\$4 and programmable and camera and offset with compensat\$4	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/09/24 12:50
L23	62	702/85-95.ccls. and (milling drilling boring)	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/09/24 12:51
L22	33	((drilling bor\$4 mill \$4) and calibrat\$4 and measur\$4 and offset).ab.	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/09/24 12:51
L21	46	(drilling bor\$4 mill \$4) near machine and calibrat\$4 with compar\$4 with locat\$4	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/09/24 12:51
L28	160	calibrat\$4 with ophthalmic	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/09/24 12:52
L27	10	calibrat\$4 with lens with drill\$4	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/09/24 12:52
L26	14	calibrat\$4 near 2 drill \$4 and template	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/09/24 12:52

L25	10	calibrat\$4 with lens with drill\$4	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/09/24 12:52
L24	14	702/85-95.ccis. and (millling drilling boring) and calibrat \$4 not sensor	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/09/24 12:52
L34	0	"358/1.15".ccis. and (millling drilling boring) and calibrat \$4 not sensor	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/09/24 13:43
L33	0	358/1.15.ccis. and (millling drilling boring) and calibrat \$4 not sensor	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/09/24 13:43
L32	0	358/1.13.ccis. and (millling drilling boring) and calibrat \$4 not sensor	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/09/24 13:43
L40	0	"399/81".ccis. and (millling drilling boring) and calibrat \$4 not sensor	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/09/24 13:44
L39	0	"399/9".ccis. and (millling drilling boring) and calibrat \$4 not sensor	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/09/24 13:44
L38	1	"709/219".ccis. and (millling drilling boring) and calibrat \$4 not sensor	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/09/24 13:44
L37	0	"709/218".ccis. and (millling drilling boring) and calibrat \$4 not sensor	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/09/24 13:44

L44	0	"358"/1.13.ccls. and (drilling bor\$4 mill \$4) with calibrat\$4 same two near holes	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/09/24 13:45
L43	3489	"358"/1.13.ccls. (drilling bor\$4 mill \$4) with calibrat\$4 same two near holes	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/09/24 13:45
L42	7	"358".1.13.ccls. (drilling bor\$4 mill \$4) with calibrat\$4 same two near holes	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/09/24 13:45
L41	246	"358".1.13.ccls. drilling with calibrat \$4 same holes	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/09/24 13:45
L50	0	"709"/218.ccls. and (drilling bor\$4 mill \$4) with calibrat\$4	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/09/24 13:46
L49	1	"358"/1.18.ccls. and (drilling bor\$4 mill \$4) with calibrat\$4	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/09/24 13:46
L48	3	"358"/1.15.ccls. and (drilling bor\$4 mill \$4) with calibrat\$4	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/09/24 13:46
L47	1	"358"/1.13.ccls. and (drilling bor\$4 mill \$4) with calibrat\$4	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/09/24 13:46
L46	0	"358"/1.13.ccls. and (drilling bor\$4 mill \$4) with calibrat\$4 and two near points	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/09/24 13:46

L45	0	"358"/1.13.ccls. and (drilling bor\$4 mill \$4) with calibrat\$4 and two near holes	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/09/24 13:46
L53	0	"399"/81.ccls. and (drilling bor\$4 mill \$4) with calibrat\$4	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/09/24 13:47
L52	1	"399"/9.ccls. and (drilling bor\$4 mill \$4) with calibrat\$4	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/09/24 13:47
L51	0	"709"/219.ccls. and (drilling bor\$4 mill \$4) with calibrat\$4	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/09/24 13:47

EAST Search History (Interference)

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L35	0	"358/1.15".ccls. and (milling drilling boring) and calibrat \$4 not sensor	US_PGPUB; USPAT; UPAD	OR	ON	2009/09/24 13:43
L36	2	"358/1.18".ccls. and (milling drilling boring) and calibrat \$4 not sensor	US_PGPUB; USPAT; UPAD	OR	ON	2009/09/24 13:44

9/24/2009 1:48:11 PM

C:\Documents and Settings\schang\Desktop\ShortCuts\10,5xx,xxx\10,574,980
\10,574,980.wsp